## **INSPECTION REPORT**

BP-13-00276

**PERMIT NUMBER:** 

OWNER'S NAME: SILVER FIR PROPERTIES

DATE:		10/14/2014	TYPE:	Frame-Plumb-Mech	
TIME STARTED:		10:09 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		22-11-09054-0059			
	1. gas at 15#- ok				
	2. H2O at 90#-ok				
	3. DWV on stack-ok				
	4. upstairs hydronics at 100#-ok				
	5. venting not complete				
INSTRUCTIONS: ok to insulate, see venting then					
NEXT INSPECTION: insulation					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>					