INSPECTION REPORT

PERMIT NUMBER:		BP-13-00413	OWNER'S NAME:	DEFOOR	
DATE:		9/11/2015	TYPE:	Re-inspection	
TIME STARTED:		2:30 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		19-17-35053-0001			
	1. **shear designations on roof framing page				
	2. 4" panel edge nailing missing on upper sheets on garage shearwalls. Circled on plan				
	3. south tall garage wall is P-6. Requires panel edge blocking and nailing along entire wa				
I	II height				
4	4. hold downs ok				
INSTRUCTIONS: complete above, call for re-inspection					
NEXT INSPECTION: re-inspection					
RE-INSPECTION FEE DUE? YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	iessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					