INSPECTION REPORT

PERMIT NUMBER:	BP-13-00703	OWNER'S NAME:	BERTEIG
DATE:	9/2/2015	TYPE:	Final
TIME STARTED:	3:03 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-16-02000-0007		
1. CO detector in loft			
2. gas fireplace not operable			
3. CO detector outside sleeping room downstairs not installed			
4. no results of blower door test posted			
5. whole house ventilation requirements not met. Whole house fan on timer, (must have vente			
d windows), or integrated fresh air to furnace needed			
6. access and septic not signed off on permit card			
7. water heater and heat pump both meet .5 credits to equal 1 credit total met5 cred			
its still needed			
8. Address not posted			
9. Fire marshal inspection not signed off for tank placement and below ground gasline			
INSTRUCTIONS: complete above			
NEXT INSPECTION: re inspection			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
<u>iessica.contratto</u> @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506