INSPECTION REPORT

PERMIT NUMBER:		BP-13-00725	OWNER'S NAME:	GREER	
DATE:		10/13/2014	TYPE:	Insulation	
TIME STARTED:		2:40 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		18-20-03000-0007			
1	. draftsto	pp at return duct not com	plete		
2	2. insulation shield around stove pipe to maintain 1" clearance to combustibles				
3	3. has chimney pipe been properly flashed/sealed at roof flashing?				
4. fresh air to woodstove still needs to be moved					
5	5. insulation ok				
INSTRUCTIONS: complete above, do not cover. call for re-inspection					
NEXT INSPECTION: re-inspection					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
jessica.contratto @co.kittitas.wa.us					
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					