## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00734	OWNER'S NAME:	EATON
DATE:	2/29/2016	TYPE:	Insulation
TIME STARTED:	10:00 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-30000-0022		
<ol> <li>Insulation ok. Apply vapor barrier or use PVA primer on drywall</li> <li>DWV on stack -ok</li> <li>Water leaking at exterior of house. Stand pipe cap next to foundation and under upright 2x6 in the ground away from house</li> <li>Range hood must be 100 CFM exhaust rate. 4" duct will not work. Must be minimum of 6" ducting.</li> </ol>			
INSTRUCTIONS: Ok to cover, see range exhaust at final. Exhaust hood or microwave can vent directly out the wall as supplied. Address leaks at exterior septic as needed. One fresh air wall port will be needed with whole house fan at final. Contact with questions- 962-7695  NEXT INSPECTION: Final			
NEXT INSPECTION:	Final		
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506