## **INSPECTION REPORT**

PERMIT NUMBER:	BP-13-00742	OWNER'S NAME:	ROSENBERRY
DATE:	11/13/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	4:55 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-14000-0007		
1. DWV not on test			
2. H2O a	t 80#/15-ok		
3. mecha	nical ok		
4. framing	g/trusses ok		
INSTRUCTIONS: ok to insulate, see DWV on test then			
NEXT INSPECTION: i	nsulation		
RE-INSPECTION FEE I	DUE? NO YES	3	\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.kitt</u> 1 N. Ruby Street, Suite 2, Ellensburg, V		
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ● Main Office Line: 509-962-7506			