INSPECTION REPORT

PERMIT NUMBER:	BP-13-0674	OWNER'S NAME:	BACK COUNTRY
DATE:	7/22/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	11:20 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-15-07060-0009		
DWV on s	stack		
H2O is liv	re		
seal duct penetrations in stairwell area through floor			
Framing/trusses OK			
rough in plumbing OK			
mechanical OK			
fireplace	OK		
INSTRUCTIONS: see holes sealed at insulation			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 			

INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506