INSPECTION REPORT

PERMIT NUMBER:	BP-14-00216	OWNER'S NAME:	CORBURN
DATE:	11/9/2015	TYPE:	Framing
TIME STARTED:	2:40 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	21-14-34059-0001		
1. Mechanical Corrections OK. Gas Line at 15#/15min.			
2. Shear Corrections OK. Engineering On File.			
3. Outdoor Fireplace Rough in Not Complete.			
4. Framing OK.			
INSTRUCTIONS: OK to Insulate.			
NEXT INSPECTION: Insulation.			
RE-INSPECTION FEE DUE? V NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
ieremv.haberman @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			