## **INSPECTION REPORT**

PERMIT NUMBER:		BP-14-00223	OWNER'S NAME:	PDQ CONSTRUCTION	
DATE:		7/30/2014	TYPE:	Insulation and mechanical	
TIME STARTED:		3:21pm	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-12065-0001			
	range ver	nt Ok			
	Still need 2 SDS screws at 16" o.c. on deck ledger				
	see letter for rafter cut at interior shear inspection				
INSTRUCTIONS: complete above. see at next inspection					
NEXT INSPECTION: interior shear					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •					

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506