## **INSPECTION REPORT**

PERMIT NUMBER:		BP-14-00258	OWNER'S NAME:	DENEEN	
DATE:		7/24/2014	TYPE:	Shearwalls	
TIME STARTED:		4:23 PM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		20-14-12067-0005			
	ok to insu	insulate and cover interior 2W4 walls			
	exterior s	exterior shear OK			
_					
INSTRUCTIONS: ok to cover, see interior before sheetrock					
NEXT	INSPECTION: 1	rame/plumb/mech			
RE-IN	SPECTION FEE I	OUE? NO YES		\$	
	IF REQ	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION	
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	,,,,,,	jessica.contratto		ittitas.wa.us	
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>					