INSPECTION REPORT

PERMIT NUMBE	ER: BP-14-00382	OWNER'S NAME:	BRAIN
DATE:	11/12/2014	TYPE:	Frame-Plumb-Mech
TIME STARTED:	3:14 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	18-18-36077-0006		
1. H20	 Dat 70#/15-ok		
2. DWV at 8#/15-ok			
3. truss bracing C4,C5,C6			
4. dryer vent not installed			
5. see gas piping before cover			
6. sup	6. support heat vents properly		
INSTRUCTIONS: ok to insulate, see above corrections then			
NEXT INSPECTION	^{DN} : insulation		
RE-INSPECTION	FEE DUE? NO YES	1	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
• INS	SPECTION REQUEST LINE: www.co.kitt 411 N. Ruby Street, Suite 2, Ellensburg, \		