INSPECTION REPORT

PERIVITI	NUMBER:	BP-14-00421	OWNER'S NAME:	SFAY LLC	
DATE:		9/17/2014	TYPE:	Re-inspection	
TIME STARTED:		12:28 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		20-15-20058-0142			
1	1. Finish	up A35 clips per shear s	chedule.		
2	2. Will see LSL beam near garage wall at framing inspection.				
INSTRUCTIONS: Complete Above, then OK TO COVER.					
NEXT INSPECTION: EXTERIOR SHEARWALLS					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 					