INSPECTION REPORT

PERMIT NUMBER:	BP-14-00421	OWNER'S NAME:	SFAY LLC
DATE:	2/10/2015	TYPE:	Framing
TIME STARTED:	10:55 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-20058-0142		
1. Install	Vapor Barrier Behind Tu	b and Shower	Enclosures.
2. Bracing on both sides of B2 Truss missing.			
3. Truss Bracing Both Sides of D2 Truss Missing.			
4. Incorrect Header Over Upstairs Hall Bathroom Window Over Shower.			
5. 4/S2 Over Stairwell Shearwall to Roof Deck.			
6. 9/S1 Not Complete at Bedroom 4 Wall			
7. Strap Top/Bottom Plate at Bedroom 4 Fireplace Wall			
8. Hangers on Stair Stringers			
INSTRUCTIONS: Complete Corrections Above. Ok to Insulate.			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jeremy.haberman @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			