INSPECTION REPORT

PERIVITI NUIVIBER:	BP-14-00437	OWNER'S NAME:	HELGESON
DATE:	11/10/2014	TYPE:	Plumbing
TIME STARTED:	11:35 AM	INSPECTOR:	Amber Green
MAP NUMBER:	19-15-08050-0004		
1. DWV a	at zero.		
2. Could not locate gauge on H2O lines.			
3. Insulate behind shower.			
4. Could not locate permit on site.			
INSTRUCTIONS: Systems must be on test for inspection. Complete Above. Re-Call			
	·	·	
NEXT INSPECTION:	Re-Inspection		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
amber.green @co.kittitas.wa.us			
	TION REQUEST LINE: <u>www.co.kitti</u> 1 N. Ruby Street, Suite 2, Ellensburg, V		
i	,		