



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-14-00437 OWNER'S NAME: HELGESON
DATE: 12/10/2014 TYPE: Frame-Plumb-Mech
TIME STARTED: 12:21 PM INSPECTOR: Jessica Contratto
MAP NUMBER: 19-15-08050-0034

	1. truss bracing A, A1, C
	2. flex ductwork cannot be sleeved in pipe. Duct must be pipe where penetrating fire separ
	ation
	3. framing ok

INSTRUCTIONS: ductwork needs to be addressed before ceiling insulation. Fix and call for re-inspection. ok to insulate walls. see truss bracing then

NEXT INSPECTION: wall insulation/ mechanical

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jessica.contratto @co.kittitas.wa.us

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506