## **INSPECTION REPORT**

PERMIT NUMBER:	BP-14-00537	OWNER'S NAME:	PHIS
DATE:	10/16/2015	TYPE:	Final
TIME STARTED:	12:10 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29051-0092		
1. Sewer connection letter needed			
2. Blower door test results not on site			
3. CO detector needed outside bunk room. Plug in type acceptable			
4. Seal gaps around furnace duct and pipes in garage			
5. Multiple runs of flex duct in crawl are smashed and run unnecessarilly under plumbing			
pipes causing poor performance of heating system			
INSTRUCTIONS: complete above, call for re-inspect. Do not occupy intil final is complete			
NEXT INSPECTION: Re-final			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			