INSPECTION REPORT

PERMIT NUMBER:		BP-14-00731	OWNER'S NAME:	LANDEN	
DATE:		9/17/2015	TYPE:	Exterior shear	
TIME STARTED:		10:53 AM	INSPECTOR:	Jessica Contratto	
MAP NUMBER:		21-13-17050-0001			
	1. galv. nails in bottom plate where noted by Erik				
	2. 4 Hold downs at deck entrance at main floor need clarification as to attachment to beam				
	below. Hold downs not in at this time				
	3. note: Zmax hangers required for treated lumber on deck, or protect with rubberized				
	membrane				
	4. tighten up nailing in few areas (Erik noted on house)				
	5. all other hold downs ok				
	6. all other exterior nailing ok				
INSTRUCTIONS: complete few nailing corrections, ok to cover exterior. Obtain clarification of fix from					
engineer for hold down issue at front deck wall					
NEXT INSPECTION: plumbing/mech					
RE-INSPECTION FEE DUE? YES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	<u>iessica.contratto</u> @co.kittitas.wa.us				
 INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 					