## **INSPECTION REPORT**

OWNER'S NAME: BV RESORT HOMES

PERMIT NUMBER:	BP-14-00735	OWNER'S NAME:	BV RESORT HOMES
DATE:	1/29/2015	TYPE:	Floor framing
TIME STARTED:	1:51 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-29050-0074		
1. Joist H	langers in Contact with F	T plate not ZM	1AX.
2. Squash blocking on front of structure not in place.			
3. Interior Point Loads OK.			
4. Interior Joist/Beam/Post Connection OK.			
INSTRUCTIONS: Correct Above. See Blocking at Framing. Email Pictures of Hanger Protection.			
NEXT INSPECTION:	Shearwalls		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jeremy.haberman @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			