## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00735 OWNER'S NAME: EQUITY TRUST CO FB

DATE:		7/17/2015	TYPE:	Mechanical and plumbir
TIME STARTED:		12:15 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		20-15-29050-0074		
1.	1. gas at 20#-ok. See patio gas line on test later			
2.	2. draftstops needed at attic duct penetrations			
3.	3. DWV on stack-ok			
4.	4. H2O is live-ok			
5.	5. living room fireplace framing not complete			
INSTRUCTIONS: see draftstops at framing. see patio gas at framing. Plumbing ok				
NEXT INSPECTION: framing				
framing				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>				