INSPECTION REPORT

BP-14-00735

PERMIT NUMBER:

OWNER'S NAME: EQUITY TRUST

DATE:		7/24/2015	TYPE:	Framing				
TIME STARTED:		9:46 AM	INSPECTOR:	Jeremy Haberman				
MAP NUMBER:		20-15-29050-0	074					
	1. B01 Tr	uss Not Per Truss	Sheet.					
	2. Top Chord of FS01 Truss Cut. OK from Truss Manufacturer Required.							
	3. Windows In Bonus Over Garage Not Egress. Bottom Edge of Opening Higher than 44".							
	4. Incomplete Plan Set. Full Set of Approved Drawings Required for Inspection.							
	5. Engineer Approval Required for Rafter to Top Plate Connection in Bonus Room/Bedroom #5.							
	See Deta	ail 1/S-6.0						
	6. Top Plate Strap Required in Bonus Bathroom.							
	7. Over Framing at Bonus Room/Bedroom#5 Not Constructed Per Plan. See Detail 10/6-6.0							
	8. Bonus Room/Bedroom #5 Outlookers Not Per Plan. Engineers Correction Required.							
	9. Attic/Sto	orage Access Openi	ngs Left and Right of N	Media Closet Not Complete.				
	10. Media	a Closet Exhaust F	an Not Connected t	o Duct				
	11. Strap Required at Top Plate Break in stairway to Bonus Room.							
	12. Positive Connection Required on Over Framing at Bedrooms #3 and #4.							
INSTRUCTIONS: MAke Corrections Above. DO NOT COVER. DO NOT INSULATE.								
NEXT INSPECTION: Re Inspection								
RE-INSPECTION FEE DUE? VES \$								
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION								
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:								
	jeremy.haberman @co.kittitas.wa.us							
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 								

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

INSPECTION REPORT

PERMIT NUMBER:		BP-14-00735	OWNER'S NAME:	EQUITY TRUST			
DATE:		7/24/2015	TYPE:	Framing			
TIME STARTED:		9:46 AM	INSPECTOR:	Jeremy Haberman			
MAP NUMBER:		20-15-29050-0074					
	D 0						
	Page 2						
	13. All 4x6 Headers Not Per Plan.						
	14. Single Top Plate at Loft Exterior Wall @ Top Of Stairs. Detail 14/A5.						
	15. Drafts	stop at Fireplace and HV	AC Chases No	ot Complete.			
	16. Roof Framing Over Trash Room Requires Spray FoamInsulation to Make Up for Lack of Vent						
	ing.						
	17. 6x6 Posts at Great Room Lack Bearing to Foudation. 6x6 Squash Block in Floor not Beari						
	ng on Beam. Post to Foundation.						
	18. (2) Foundation Vents Visible at Time of Inspection. Provide adequate Crawl Ventilation						
	•						
	19. Horizo	ontal Strapping Where To	op Plate Sevei	ed in Laundry.			
	20. Verify Over Framing at Shed Room Over Master Tub and Laundry.						
	21. (2) TJIs Top Chords Severed at Master Bath Over Tub.						
INSTRUCTIONS: MAke Corrections Above. DO NOT COVER. DO NOT INSULATE.							
NEXT INSPECTION: Re Inspection							
RE-INSPECTION FEE DUE? VES \$							
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION							
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:							
	jeremy.haberman @co.kittitas.wa.us						

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

INSPECTION REPORT

PERMIT NUMBER:	BP-14-00735	OWNER'S NAME:	EQUITY TRUST				
DATE:	7/24/2015	TYPE:	Framing				
TIME STARTED:	9:46 AM	INSPECTOR:	Jeremy Haberman				
MAP NUMBER:	20-15-29050-0074						
Page 3							
22. Firep	place Surrounds/Chases	Not Complete.					
23. Maintain Fire Seperation at Garage Corner.							
24. Provide Continuous Studs From Plate to Plate at Kitchen Wall.							
25. Provide Full Bearing Under Porch Bean Pocket at Kitchen Wall.							
26. Provide	26. Provide Detail for 12x12 Porch Post Connection at Base. No Visible Possitive Connectio						
n.							
27. Verify Interior Shear at ReInspection With Permit Set Drawings.							
28. Verify All Outlookers per Engineer Letter.							
INSTRUCTIONS: MAke Corrections Above. DO NOT COVER. DO NOT INSULATE.							
NEXT INSPECTION:	Re Inspection						
RE-INSPECTION FEE DUE? VES \$							
IF REC	QUIRED, RE-INSPECTION FEES MUST BE	E PAID PRIOR TO SCHE	DULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:							
	jerem	ny.haberman @co.k i	ittitas.wa.us				
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 ◆ 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506 							