INSPECTION REPORT

PERMIT NUMBER:	BP-14-00735	OWNER'S NAME:	EQUITY TRUST
DATE:	8/18/2015	TYPE:	Insulation
TIME STARTED:	11:37 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-29050-0074		
1. Floor joist	chords cut out around return du	uct in crawl stair are	ea
2. truss fix ok			
3. bonus room egress fix ok			
4. rafter tail fix per 1/S6 ok			
5. foundation vents not in yet. See by final			
6. insulation ok			
7. draftstops ok			
8. clearance to combustibles on bath tub fireplace chimney. Take pics			
9. provide engineer approval for all thread for post connection at 12 x 12 posts at exteri			
or			
10. patio gas line to be tested			
INSTRUCTIONS: ok to cover. See vents and joist fix in crawl at final. Complet above			
NEXT INSPECTION: final			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 			

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506