INSPECTION REPORT

PERMIT NUMBER:	BP-14-00771	OWNER'S NAME:	EVERGREEN VALLEY LLC
DATE:	3/23/2015	TYPE:	Framing
TIME STARTED:	10:36 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-14-12058-0001		
1. Trusse	es OK.		
2. Verify Center Front Porch Post Connection at Insulation.			
3. DWV OK. Stack Test.			
4. Supply Not @ 50#. Verify Test Pressure at Insulation.			
5. Bath Fans Not Connected to Exterior. Verify at Insulation.			
6. Install Fire Blocking and 3/4" Deck Lid at Fireplace Enclosure.			
7. Gas Line Not Complete. Not On Test.			
INSTRUCTIONS: OK to Insulate.			
NEXT INSPECTION:	nsulation/ReInspect		
RE-INSPECTION FEE I	DUE? NO YES		\$
IF REQU	UIRED, RE-INSPECTION FEES MUST BE	PAID PRIOR TO SCHE	DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jeremy.haberman @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			