INSPECTION REPORT

PERMIT NUMBER: BP-14-00785 OWNER'S NAME: BACK COUNTRY

DATE:	//1//2015	TYPE:	Floor framing
TIME STARTED:	10:02 AM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-07060-0011		
1 Correcti	ons 1, 4, 5 & 7 Ok		
	oor framing corrections 2, 3 &	6 @ Framing	
Z. Verny no	oor training corrections 2, 3 &	10 @ Framing	
INSTRUCTIONS: Verify floor framing corrections 2, 3 & 6 @ Framing			
NEXT INSPECTION:	Exterior Shear		
RE-INSPECTION FEI	E DUE? NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
Q	UESTIONS? PLEASE CONTACT THE I	NSPECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		iustin.bennett @co	o.kittitas.wa.us
	CTION REQUEST LINE: www.co.		
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			