## **INSPECTION REPORT**

PERMIT NUMBER: BP-14-00826 OWNER'S NAME: ERDMAN

DATE:	5/20/2015	TYPE:	Exterior shear
TIME STARTED:	3:26 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	18-18-31051-0004		
1 0040 0 1	OTUDOL M M . El	0 0 11 14	1001
1. CS16 & LSTHD8's Missing from Main Floor. See Bubbled Areas on 'S2'.			
INSTRUCTIONS: Make Corrections Above. Call For ReInspection			
NEXT INSPECTION: Shearwall/Plumbing/Mech??			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
ieremv.haberman @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926</li> <li>Main Office Line: 509-962-7506</li> </ul>			