INSPECTION REPORT

PERMIT NUMBER:	BP-15-00055	OWNER'S NAME:	WARREN
DATE:	6/19/2015	TYPE:	Framing
TIME STARTED:	1:17 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-19-35052-0004		
1. trusses of	<		
2. framing o	k		
3. where whole house fan is used, fresh air must be brought in to all habitable rooms via			
vented windows or air inlets in wall			
4. fireplace ok			
5. gas at 28#-ok			
6. sidelight window at front door to be tempered.(within 24" of door)			
INSTRUCTIONS: ok to insulate. see tempered window and fresh air inlets at final. Fresh air can be			
obtained also through forced air system			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			