## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00056 OWNER'S NAME: LARSON

DATE:		1/7/2016	TYPE:	Exterior shear	
TIME STARTED:		5:06 PM	INSPECTOR:	Jeremy Haberman	
		20-14-14050-0924			
	Holdowns Missing in (2) Locations, Bubbled on Permit Set.				
	2. HDU's Must Connect to (2) Full Height Members. Condition Exists Throughout.				
INSTR	RUCTIONS: (	OK to Cover Exterior			
NEXT	INSPECTION:	Shear ReInspect/Plum	b/Mech		
RE-IN	SPECTION FEE	DUE? NO	YES	\$	
			ES MUST BE PAID PRIOR TO SCH		
	QI	UESTIONS? PLEASE CONTAC	T THE INSPECTOR AT THE FOLLO		
			ieremv.haberman @co		
			<mark>vw.co.kittitas.wa.us/cds/req</mark> llensburg, WA 98926 ● Main O	uest.asp or 509-962-7694 ● ffice Line: 509-962-7506	
	<u> </u>		<b>o</b> , <b>o</b>		