INSPECTION REPORT

IIIOI ECITOR REI ORI			
PERMIT NUMBER:	BP-15-00056	OWNER'S NAME:	LARSON
DATE:	4/21/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	12:39 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-14050-0924		
1. Gas @ 25#/15 mins - Ok 2. Supply @ 60#/15 mins - Ok 3. DWV on stack - Ok 4. Plumbing rough in Ok 5. Exterior shear corrections not complete INSTRUCTIONS: Complete exterior shear corrections			
NEXT INSPECTION: Mechanical			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
	ADDRESS:	iustin.bennett @	co.kittitas.wa.us

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506