INSPECTION REPORT

PERMIT NUMBER:	BP-15-00081	OWNER'S NAME:	NELSON SIDING
DATE:	4/27/2015	TYPE:	Frame-Plumb-Mech
TIME STARTED:	2:32 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	19-14-03000-0085		
1. hanger	fill in floor joists above	main floor bath	S
2. fill in cut out stud in wall behind fireplace			
3. DWV on stack-ok			
4. H2O at 70#-ok			
5. gas at 20#-ok			
6. mechanical ok			
7. see range vent by final			
8. rough in plumbing ok			
	•		
INSTRUCTIONS: complete above, ok to insulate			
NEXT INSPECTION:	nsulation		
RE-INSPECTION FEE DUE? NO YES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
jessica.contratto @co.kittitas.wa.us			
● INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ●			

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506