INSPECTION REPORT

OWNER'S NAME: CASCADE VIEW INC

BP-15-00110

PERMIT NUMBER:

DATE:		5/22/2015	TYPE:	Frame-Plumb-Mech	
TIME STARTED:		1:39 PM	INSPECTOR:	Amber Green	
MAP NUMBER:		18-18-27071-013	8		
	1. Complete clips from I-joists to top plate at cantilevered floor per sheet L-1.				
INSTRUCTIONS: Ok to Insulate.					
NEXT INSPECTION: Insulation					
RE-IN	SPECTION FEI	E DUE? NO	YES	\$	
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	amber.green @co.kittitas.wa.us				
	■ INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ■ 411 N. Rubu Street, Suite 3. Ellensburg, WA 08036 a Main Office Lines 500 063, 7506				
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					