INSPECTION REPORT

PERMIT NUMBER:

BP-15-00111

OWNER'S NAME: CASCADE VIEW INC

DATE:		5/15/2015	TYPE:	Exterior shear	
TIME STARTED:		9:09 AM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		18-18-27071-0146			
	4 =	14/ II D: 14 (E 4 14:		D 14	
	1. Exterior Wall Right of Entry Missing Holdown Bolt				
	2. Holdowns Must Connect to (2) Full Height Studs. Will Accept CS Strapt On Trimmer To Top				
	Plate.				
INSTRUCTIONS: Make Corrections. Call for Reinspection.					
NEXT INSPECTION: Re Inspect					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					