



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00111 OWNER'S NAME: CASCADE VIEW
DATE: 6/3/2015 TYPE: Frame-Plumb-Mech
TIME STARTED: 12:00 PM INSPECTOR: Jeremy Haberman
MAP NUMBER: 18-18-27071-0146

	1. Corrections OK.
	2. Plumbing Rough OK. DWV on Stack Test. Supply @ 60#/15min.
	3. Range Vent Not Installed.
	4. Vented Windows Required in All Habitable Rooms on First Floor.
	5. Interior Shear OK.
	6. Girder Truss Not Clipped to Plate at Either End.
	7. Provide Coil Strap from Plate to Plate at South End of GluLam Over Arched Window Wall.
	8. Strap Top Plate Break in Den/Guest Room.
	9. Pressure Treated 4x4 Missing at Entry Porch Roof.

INSTRUCTIONS: Make Corrections Above. OK to Insulate

NEXT INSPECTION: Insulation.

RE-INSPECTION FEE DUE? ☒ NO ☐ YES \$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ jeremy.haberman @co.kittitas.wa.us

• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506