INSPECTION REPORT

IIIOI ECITOR REL ORI			
PERMIT NUMBER:	BP-15-00132	OWNER'S NAME:	REMETO
DATE:	8/19/2016	TYPE:	Gas piping
TIME STARTED:	9:48 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-26063-0013		
 Gas at 17#-ok DWV on stack-ok H20 is live pressure-ok Exhaust duct ok Supply duct ok Fireplace rough in ok Solar panels on structure require permitting and inspections 			
INSTRUCTIONS: Obtsin permit for solar if not already. Complete electrical install and L&I inspection			
NEXT INSPECTION:	Framing		
RE-INSPECTION FEE	DUE? V NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506