INSPECTION REPORT

PERMIT NUMBER:	BP-15-00156	OWNER'S NAME:	CARBARY
DATE:	2/2/2016	TYPE:	Framing
TIME STARTED:	1:36 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	20-14-24050-0316		
 Interior shear ok Complete squash blocking @ theater room Provide engineer fix for window header in garage Framing Ok Previous corrections not complete Complete fire blocking @ stair for bonus room INSTRUCTIONS: Complete items above/Email engineer fix with photo/Once complete ok to insulate			
NEXT INSPECTION:			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
	QUESTIONS? PLEASE CONTACT THE I ADDRESS:	NSPECTOR AT THE FO iustin.bennett @	

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506