INSPECTION REPORT

| INSPECTION REPORT | | | |
|--|------------------|---------------|--------------------|
| PERMIT NUMBER: | BP-15-00156 | OWNER'S NAME: | CARBARY |
| DATE: | 4/22/2016 | TYPE: | Stove or fireplace |
| TIME STARTED: | 11:53 AM | INSPECTOR: | Jessica Contratto |
| MAP NUMBER: | 20-14-24050-0316 | | |
| 1. Main floor fireplace rough in ok 2. Range hood requires make up air if over 400 cfm 3. basement fireplace not roughed in yet. See before cover 4. Has revision been completed for added mechanical room. Room not walled in or complete yet INSTRUCTIONS: have make up air system completed by final | | | |
| NEXT INSPECTION: fireplace | | | |
| RE-INSPECTION FEE | | | \$ |
| IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION | | | |
| QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL | | | |

INSPECTION REQUEST LINE: 509-962-7694

ADDRESS:__

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

iessica.contratto @co.kittitas.wa.us