## **INSPECTION REPORT**

INSI ECHON KEI OKI			
PERMIT NUMBER:	BP-15-00165	OWNER'S NAME:	BV RESORT HOMES
DATE:	6/13/2016	TYPE:	Framing
TIME STARTED:	1:03 PM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:	20-15-19051-0032		
<ol> <li>Trusses OK.</li> <li>Interior Shear Corrections Outstanding. Penetrations In Shear Wall and Missin g 6x8 Post Not Addressed. Builder Is WEaiting For Letter from Engineer.</li> <li>Beam R13 Not Per Plan.</li> <li>Beam R Rafter Detail 1/S6 Not Per Plan. Provide Engineers Approval.</li> <li>Strap Beam R9 to Girder Per Note on S3.</li> <li>Gas Line Test OK. 22#/15min. OK.</li> <li>Fireplace Rough In OK.</li> <li>Front Porch Post to Beam Connection Not Per Plan.</li> <li>Install Shear Clips at Garage Shearwall Per 8/S2.</li> <li>Interior Shear at Bedroom #1 Not Per 4/S4.</li> <li>HVAC Main Penetrates Interior Shear Wall.</li> <li>Provide Engineers OK. For Holes In Floor Joist Above Laundry.</li> <li>6x6 at Hallway to Master Not 6x8 Per Plan.</li> </ol> INSTRUCTIONS: OK to Insulate Walls. NEXT INSPECTION: Insulation			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE			\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION  QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>ieremv.haberman</u> @co.kittitas.wa.us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506