## **INSPECTION REPORT**

**PERMIT NUMBER:** 

BP-15-00179

OWNER'S NAME: WEBSTER

DATE:		7/15/2015	TYPE:	Floor framing	
TIME STARTED:		2:13 PM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		20-15-29051-0089			
	1. Floor Framing Over Crawl OK.				
	2. Under Floor Shear OK.				
	3. TRUSSED FLOOR SYSTEM OVER BASEMENT NOT INSPECTED.				
INSTRUCTIONS: OK to Sheet Floor					
NEXT INSPECTION: Shearwalls					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506					