INSPECTION REPORT

TYPE:

OWNER'S NAME: WEBSTER

Gas piping

PERMIT NUMBER: BP-15-00179

DATE:

10/21/2015

MAP NUMBER: 20-15-29051-0089 1. H2O at 70# working pressure-ok 2. Leak in upstairs DWV 3. Gas at 22#-ok INSTRUCTIONS: Fix leak, re-inspect DWV
2. Leak in upstairs DWV 3. Gas at 22#-ok
2. Leak in upstairs DWV 3. Gas at 22#-ok
3. Gas at 22#-ok
INSTRUCTIONS: Fix leak, re-inspect DWV
NEXT INSPECTION: re-inspect
RE-INSPECTION FEE DUE? VES \$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:
iessica.contratto @co.kittitas.wa.us
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506