



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00217

OWNER'S NAME: ANDERSON

DATE: 9/25/2015

TYPE: Floor framing

TIME STARTED: 11:22 AM

INSPECTOR: Jessica Contratto

MAP NUMBER: 19-20-35000-0001

	1. add rubberized flashing material under hangers on treated sill
	2. gusset missed post to beam splice

INSTRUCTIONS: complete above, take pics of completed flashing before cover. Email to below or have available for inspector to see. Ok to cover when complete

NEXT INSPECTION: shearwalls

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:

_____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

• **INSPECTION REQUEST LINE:** www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 •

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506