## **INSPECTION REPORT**

OWNER'S NAME: HANSEN

BP-15-00260

**PERMIT NUMBER:** 

DATE:		6/1/2015	TYPE:	Exterior shear	
TIME STARTED:		3:17 PM	INSPECTOR:	Jeremy Haberman	
MAP NUMBER:		16-20-04000-0003			
	1. Exterio	Exterior Brace Wall Panels OK.			
	2. Under Flo	Inder Floor Framing Inspection Not Completed. Verify Floor Framing and Crawl Access at			
	Framing.	aming.			
INSTRUCTIONS: OK to Cover Exterior					
NEXT INSPECTION: Plumb/Frame/Mech					
RE-INSPECTION FEE DUE? VES \$					
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:					
	jeremy.haberman @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 •					
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506					