## **INSPECTION REPORT**

PERMIT NUMBER: BP-15-00387 OWNER'S NAME: FORTUNE CREEK LLC

DATE:	8/18/2015	TYPE:	Floor framing
TIME STARTED:	3:01 PM	INSPECTOR:	Justin Bennett
MAP NUMBER:	19-15-07061-0031		
1. Correct	ctions Ok		
Floor Framing Ok     Ok to cover			
3. Ok to cover			
INSTRUCTIONS: Ok to cover			
NEXT INSPECTION: Exterior Shear			
RE-INSPECTION FE	E DUE? V NO	YES	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iustin_bennett @co.kittitas.wa.us			
<ul> <li>INSPECTION REQUEST LINE: <u>www.co.kittitas.wa.us/cds/request.asp</u> or 509-962-7694 ◆</li> <li>411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 ◆ Main Office Line: 509-962-7506</li> </ul>			