INSPECTION REPORT

TYPE:

PERMIT NUMBER:

DATE:

BP-15-00390

7/17/2015

OWNER'S NAME:

BISSONETTE

Re-inspection

TIME STARTED:		11:42 AM	INSPECTOR:	Jeremy Haberman
MAP NUMBER:		17-19-05051-0002		
	1. Floor	Framing Corrections OK	•	
	2. Setback Verification Not Complete. See Previous Corrections.			
INSTR				tback Verification. NO FURTHER
		NSPECTION WITHOUT SETBA	CK VERIFICATIC	JN.
NEXT	INSPECTION:	Setbacks/Shearwall		
RE-IN	SPECTION FEE	E DUE? NO YE	S	\$
	IF REC	QUIRED, RE-INSPECTION FEES MUST B	E PAID PRIOR TO SC	HEDULING A RE-INSPECTION
	QI	JESTIONS? PLEASE CONTACT THE INSP	PECTOR AT THE FOLL	OWING E-MAIL ADDRESS:
		jeren	ny.haberman @cc	o.kittitas.wa.us
		CTION REQUEST LINE: www.co.kit 11 N. Ruby Street, Suite 2, Ellensburg,		
			TILL OCCUPANT	