INSPECTION REPORT

PERMIT NUMBER: BP-15-00390 OWNER'S NAME: BISSONETTE

DATE:		8/27/2015	TYPE:	Framing
TIME STARTED:		10:45 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:		17-19-05051-0002	2	
	1. stamped	truss sheets not on site)	
	2. header straps to top plate needed per 8/6 in dining bump out			
	3. overframed areas not substantially posted down per plan note page 5			
	4. water will need to be at 50# min for passing inspection			
	5. fireplace chimney needs to be installed for insulation inspection to verify clearance t			
	o combustibles			
	6. vented windows required with whole house fan. Integrated fresh air to furnace also acce			
	ptable			
	7. revision required for garage converted to living space before proceeding			
	8. attic access needed for garage room			
	9. L&I inspection not complete for cover			
INSTRUCTIONS: ok to insulate walls only. Submit recvisions and have water on proper test and				
stamped truss sheets for next inspection. Rough in fireplace chimney				
NEXT INSPECTION: insulation/corrections				
RE-INSPECTION FEE DUE? VES \$				
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION				
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:				
iessica.contratto @co.kittitas.wa.us				
• INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506				