INSPECTION REPORT

PERMIT NUMBER:	BP-15-00448	OWNER'S NAME:	SHCHEDRIN
DATE:	10/5/2016	TYPE:	Insulation
TIME STARTED:	12:08 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	22-11-15051-0007		
 Outdoor fireplace ok Insulation ok. R-60 in all ceiling, 2" of sprayfoam for R-13, R-13 batts over top in walls. Insulation and U-value of .23 on windows meets energy credit 1b for 1 credit Furnace meets .5 credits Indoor fireplace still needs inspected before cover 			
INSTRUCTIONS: Ok to cover all but fireplace NEXT INSPECTION: Fireplace			
RE-INSPECTION FEE	DUE? NO YES	PAID PRIOR TO SCHE	\$ DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS:iessica.contratto @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506