## **INSPECTION REPORT**

PERMIT NUMBER:	BP-15-00492	OWNER'S NAME:	MERITAGE
DATE:	1/20/2016	TYPE:	Framing
TIME STARTED:	11:27 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-20058-0016		
Move lineset away from B-vent in attic area			
2. Heat trunk above bed 3 not screwed/sealed at elbow			
3. H1 clips on trusses			
4. Girder truss C04- strap down both ends. Strap to top plate at bed 3 end			
5. Post down under girder truss at master bath toilet room header			
6. Insulation shield at water heater b-vent in attic			
7. Properly apply mastic to proper thickness to seal ductwork			
INSTRUCTIONS: complete above, ok to insulate. Spray foam areas where proper venting cannot be			
achieved			
NEXT INSPECTION: insulation			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
• INSPECTION REQUEST LINE: <a href="www.co.kittitas.wa.us/cds/request.asp">www.co.kittitas.wa.us/cds/request.asp</a> or 509-962-7694 • 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506			