INSPECTION REPORT

PERMIT NUMBER:	BP-15-00554	OWNER'S NAME:	HABERMAN
DATE:	10/27/2015	TYPE:	Framing
TIME STARTED:	10:36 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-16-27050-0002		
1. Shear also	o inspected		
2. Front of garage not per detail 5/D1. Header required to extend over shearwalls at			
garage door, straps over header, stagger nail sheathing to header 3" oc. All panel edge			
nailing at 3" also			
3. Outlookers not per detail 2/D1. LTP5 clips top plate to truss, outlookers at 24".			
Currently at 48"			
4. stamped truss sheets not on site			
5. Man door added in place of one garage door. Verify installed header is correctly sized			
6. Window placed in back shearwall			
7. Windows omitted on sides-ok			
INSTRUCTIONS: complete above or obtain engineer approval or fix. Do not cover			
NEXT INSPECTION: re-inspect			
RE-INSPECTION FEE DUE? VES \$			
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
<u>iessica.contratto</u> @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			