INSPECTION REPORT

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00564	OWNER'S NAME:	VAN TILBURG
DATE:	4/13/2016	TYPE:	Multiple (see notes)
TIME STARTED:	12:20 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	21-14-09058-0004		
 Hydronics at 100#-ok DWV on stack-ok H20 is live at over 50#-ok Garage ceiling separation can not have can light penetrations Interior framing ok Upper wall framing ok Verify egress windows at insulation 			
INSTRUCTIONS: Ok to insulate once electrical has passed inspection			
NEXT INSPECTION: Insulation			
RE-INSPECTION FEE	DUE? NO YES	PAID PRIOR TO SCHE	\$ DULING A RE-INSPECTION
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL			
ADDRESS: <u>iessica.contratto</u> @co.kittitas.wa.us			

INSPECTION REQUEST LINE: 509-962-7694

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506