INSPECTION REPORT

PERMIT NUMBER:	BP-15-00612	OWNER'S NAME:	KLOCKNER		
DATE:	12/2/2016	TYPE:	Framing		
TIME STARTED:	10:03 AM	INSPECTOR:	Justin Bennett		
MAP NUMBER:	18-18-14000-0001				
 Exterior Shear cannot be verified - lap siding installed HD in house not exposed - need to verify (clouded on dwgs) Range hood not installed Fan in upstairs bathroom not installed SD/CO2 not installed @ top of stairs Ceiling height @ stair landing is 6' clear Ceiling insulation is 6" of Rigid Deck beam not per plan Deck post not per plan Deck roof trusses not visible Handrail not installed @ interior stairs Garage man door not self closing Patch inspection hole @ fire separation Headers Ok Egress windows Ok Wall Insulation Ok 					
INSTRUCTIONS: Complete above/Re-Inspection					
NEXT INSPECTION: Re-Inspection					
RE-INSPECTION FEE	DUE? NO YES		\$		
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
	QUESTIONS? PLEASE CONTACT THE I				
	ADDRESS:	iustin.bennett @	co.kittitas.wa.us		
INSPECTION REQUEST LINE: 509-962-7694					

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506

INSPECTION REPORT

PERMIT NUMBER:	BP-15-00612	OWNER'S NAME:	KLOCKNER		
DATE:	12/2/2016	TYPE:	Framing		
TIME STARTED:	10:03 AM	INSPECTOR:	Justin Bennett		
MAP NUMBER:	18-18-14000-0001				
Page 2					
17. L&I inspection	n complete				
INSTRUCTIONS: Complete above/Re-Inspection					
NEXT INSPECTION:					
NEXT INSPECTION.	Re-Inspection				
RE-INSPECTION FEE DUE? VES \$ IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION					
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL					
	ADDRESS:	iustin.bennett @	co.kittitas.wa.us		
INSPECTION REQUEST LINE: 509-962-7694					

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506