INSPECTION REPORT

PERMIT NUMBER:	BP-15-00636	OWNER'S NAME:	CARTER
DATE:	1/13/2016	TYPE:	Frame-Plumb-Mech
TIME STARTED:	11:04 AM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	17-20-29054-0004		
1. Gas at 30#-ok			
2. H20 at 70#-ok			
3. DWV at 5#-ok			
4. Truss uplift connectors required. Will verify requirements			
5. Truss bracing ok			
INSTRUCTIONS: ok to insulate			
NEXT INSPECTION: insulation/ trusses			
RE-INSPECTION FEE	DUE? V NO YE	S	\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL ADDRESS:			
iessica.contratto @co.kittitas.wa.us			
 INSPECTION REQUEST LINE: www.co.kittitas.wa.us/cds/request.asp or 509-962-7694 411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 Main Office Line: 509-962-7506 			