## **INSPECTION REPORT**

INSPECTION REPORT			
PERMIT NUMBER:	BP-15-00793	OWNER'S NAME:	NELSON-KAPLAN
DATE:	11/4/2016	TYPE:	Mechanical and plumbir
TIME STARTED:	4:25 PM	INSPECTOR:	Jessica Contratto
MAP NUMBER:	20-15-13050-0002		
<ol> <li>DWV at 6#-ok</li> <li>H20 at 100#-ok</li> <li>Does detail 8/S900 apply to all windows??</li> <li>Detail 15/S901 not called out. Does this apply to current conditions at all Glulam overhang beam where terminates into framed wall</li> <li>Approval onsite for change in roof rafter attachment to top plate-ok</li> </ol> INSTRUCTIONS: Complete above, corrections may or may not be necessary			
NEXT INSPECTION:			
RE-INSPECTION FEE	DUE? NO YES		\$
IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION			
QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL  ADDRESS: iessica contratto @co kittitas wa us			

**INSPECTION REQUEST LINE: 509-962-7694** 

http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx
411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506