



KITTITAS COUNTY COMMUNITY DEVELOPMENT SERVICES

INSPECTION REPORT

PERMIT NUMBER: BP-15-00878

OWNER'S NAME: STRATTON

DATE: 3/20/2017

TYPE: Framing

TIME STARTED: 12:20 PM

INSPECTOR: Jessica Contratto

MAP NUMBER: 16-20-03000-0009

1. Stamped truss sheets not on site
2. Safety glass needed at openable panes at master tub windows
3. Safety glass needed at tops of stairs in main house. Loft above garage window ok. Over 36" above stairs
4. Install H2.5 clips on rafters not covered by overframing. Overframed rafters are clipped on back side

INSTRUCTIONS: Complete above. Ok to insulate. See truss sheets at next inspection

NEXT INSPECTION: Insulation

RE-INSPECTION FEE DUE?



NO



YES

\$ _____

IF REQUIRED, RE-INSPECTION FEES MUST BE PAID PRIOR TO SCHEDULING A RE-INSPECTION

QUESTIONS? PLEASE CONTACT THE INSPECTOR AT THE FOLLOWING E-MAIL
ADDRESS: _____ [jessica.contratto @co.kittitas.wa.us](mailto:jessica.contratto@co.kittitas.wa.us)

INSPECTION REQUEST LINE: 509-962-7694

<http://www.co.kittitas.wa.us/cds/building/inspection-request.aspx>

411 N. Ruby Street, Suite 2, Ellensburg, WA 98926 • Main Office Line: 509-962-7506